

VUTEK UltraVu 3300 Printer

Originally purchased new Sept '98 \$487,950.00

Schedule of major service updates, upgrades & repairs: (last 18 months)

- 6 jet packs replaced
- Jet driver board replaced
- Carriage overflow felt pad replaced
- Pixel board replaced
- Carriage bearings serviced / replaced
- Oil Changed
- Drive belt tension adjusted
- Ink filters changed
- Tank filters changed
- Ink change-over to Vutek OEM inks
- Software Change-over to Colorburst
- Fan cleaned
- Secondary ink tanks upgraded
- Tygon tubing replaced inside carriage
- Dryer mesh kit installed
- Umbilical cables replaced
- Drive motor assembly replaced

List of Spares: (Total value approx \$35,000.00)

- 10 Jet Packs
 - 4 Primary ink tank filters
 - 3 Carriage Fan Filters
 - 1 Carriage overflow felt pad
 - 1 Cyan purge button
 - 1 Black purge button
 - 1 Magenta purge button
 - 1 Yellow purge button
 - 5 #AA70152 3-way solenoid
 - 1 #AA7015 2-way solenoid
 - 4 Secondary ink tank filters
 - 2 Secondary ink tank float sensor
 - 4 Secondary ink tank fiber optic sensor
 - 4 Secondary ink tank gaskets
 - 1 Primary ink tank
- Assortment of allen head screws, shims & fuses
- Misc computer boards: (5)#P5053-A, (9)#P5091A & (2)#P7364-A